

BORAL PEPPERTREE & MARULAN SOUTH LIMESTONE COMMUNITY CONSULTATIVE COMMITTEE

Minutes

Meeting Date: 2 November 2022

Location: Marulan South Limestone Office

CCC Members

Attendees: Gordon Kirkby (JBA Urban Planning – Independent Chairperson); Geoff Clark (representing Tallong Community Focus Group); Peter Walker (Mayor - representing Goulburn Mulwaree Council); Russell Montgomery (community representative);

Boral attendees: Les Longhurst, Michael Higgins, Chris Brown, Therese Hadjia and Kate Woodbridge.

Apologies: Charles Mendel (community representative)

Distribution: As above; Department of Planning (Georgia.Dragicevic@planning.nsw.gov.au);

Goulburn Mulwaree Council Administration (amy.croker@goulburn.nsw.gov.au)

Subject: 2 November 2022 Meeting of Boral Peppertree Quarry & Marulan South Limestone Mine CCC

Item	Description
Welcome and	Gordon opened the meeting at 3:18 pm, welcomed all members.
Introduction	
Apologies	as above
Site Inspection	A site inspection was conducted after the meeting.
Confirmation of	The Committee accept that the minutes from last meeting were an accurate record of the
minutes from	meeting.
previous meeting	
Business arising	The new Peppertree Quarry environmental report has been distributed.
Correspondence IN	<u>PTO</u>
and OUT	Department of Planning and Environment
	Submission of rehabilitation bond calculation
	EPA
	Risk Based licensing inspection
	Resource Regulator
	There were two sites visits by the regulator for lifting equipment and explosives.
	Both were standard inspections and nothing of major consequence was identified at either
	inspection.
	Goulburn Mulwaree Council
	Council visit by the Mayor, Deputy Mayor and four Council staff.
	Geoff Clark
	weather data reviews – weather station monthly reviews



MSL

Department of Planning and Environment

Assessing Environmental Management Plans (EMP's)

EPA

Environmental protection license will be amended upon approval EMP's

Resource Regulator

Mine and dump stages for Rehabilitation Management Plan (RMP) have been drafted.

Waiting on final approval of mining lease before due date for submission of RMP at end of November

Goulburn Mulwaree Council

Council visit by the Mayor, Deputy Mayor and four Council staff. The new CEO will be visiting in the next few weeks as well.

Work commenced on designs of upgrade for Marulan South Road

Progress of Operations to date

PTQ

Safety

A contractor was injured at site since the last meeting, that employee has now returned to work.

Overburden

Overburden is being stripped focusing on Southerly direction circa 1.5 million m3 has been moved.

There are traffic lights and traffic wardens on the road at the moment while that overburden is being moved.

Pit Update

Contract crushing, conveyor re-alignment (CV110).

Processing (STQ)

Some rail disruptions due to rail contractor industrial action. Temporary approval for up to 60 laden trucks daily. (Ceased 28th October)

Rain has caused some aggregate and road base production issues.

People

STQ supervisor has been filled, leading hand position, pit supervisor, temporary roles in both STQ and Primary.

MSL

Safety

The management team went offsite recently to focus on training, including safety focus seminars and workshops, safety supervision and specific hazard training eg. electrical awareness and train shunting.

Overburden

Overburden Stripping has been progressing at a steady

375,000t/month and will continue at this rate for the foreseeable future.

Processing (STQ)

Extracting at a rate of 240,000t/month. 2/3 of the limestone extracted goes to the Berrima kiln which has run smoothly. The remaining limestone is made into lime on site which goes into things like mining, agriculture and water treatment. All water along the east coast is treated with Marulan's limestone.



	People
	Celebrated milestones at the service awards. Also celebrated the retirement of Marty Saville after 30 years.
PTQ	PTQ
	Environmental Incidents (August – October 2022)
Environment	> August - nil
	> September - nil
incidents	> October – nil (1x localised oil spill)
	Complaints (August – October 2022)
	> August - nil
Complaints	> September - nil
	> October – nil
	Dust Deposition Gauges - All results are below the criteria as per the approval
Air Quality	PM10, Annual average in compliance at the boundary. No samples over 24 hour criteria
	beyond the boundary.
	TSP in compliance. PM2.5 In Compliance at the boundary
	1142.5 In Compliance at the boundary
Blasting	All blasts have complied with noise and vibration measurements requirements.
Diasting	
	Monitoring was undertaken over the 29th, 30th and 1st June/July March 2022 and 1
Noise	August/September 2022.
	Results for the June/July and August/September round are in compliance.
	Next round due in December.
	No issues with water supply or quality over the last 3 months
Surface water	Quarterly monitoring round undertaken in July – September 2022 with sampling on Thursday 18th August 2022.
	Total Nitrogen was below guideline for August samples with exception of main dam and T1
	Total dissolved solids below guideline for August samples with exception of U1
	Turbidity- Below guideline for August samples
	pH is within trigger levels for all sites
	Total phosphorus - Below guideline for August samples
	Environmental Flow - 10% environmental flow required – in compliance.



Monitoring conducted in May 2022 and September 2022. May results all good, waiting on September results. **Ground water** Results show no changes to the groundwater Artefact analysis and cataloguing is due to start in the coming weeks for approximately 30,000 Heritage artefacts. This will give us a good idea of the cultural history of the site. Approximately 65 000 artefacts have been returned to country in September Reconciliation week activity being developed onsite, potential artwork in courtyard and artefact display for staff Scar tree relocation being planned, currently undercover near the farm house. Scar tree conservation consultant has been engaged and advice provided Rehabilitation Three year plan developed for ongoing rehabilitation and maintenance 16.5ha of tree planting in spring including yellow box, gum and woodland trees. 5km of direct seeding in spring Approx 80 000m2 hydromulched Rapid visual Assessment and ecological assessment to take place in November Weed management undertaken in the last couple of months. With the focus on black berry and serrated tussock after Christmas. 33 nest boxes will be inspected around the dam area, there is a requirement to monitor them for the first few years to make sure there are no pests in the boxes, a report will be done on completion. Seed bombing was done on the Eastern emplacement rock mulch More feral goats have been removed, this has been happening on a as needs basis. The site has been contacted by National Parks regarding goats and between the two sites we will develop a plan to manage the goat population in the area as they do some damage around the sites. Annual aerial culling used to be done in the area, it will commence again to try and control numbers. **MSL MSL** Dust Deposition Gauges - All results are below the criteria as per the approval **Air Quality** PM10, Annual average in compliance at the boundary. TSP in compliance. PM2.5 in compliance. All blasts have complied with noise and vibration measurements requirements.



Blasting

Surface water

Surface water monitoring is undertaken biannually with sampling due in November 2022 which will be presented at the next CCC meeting.

Currently awaiting results which will be displayed at the next CCC meeting.

Ground water

Currently Rehabilitating the Western Overburden Elevation.

Rehabilitation



Community engagement

Goulburn Mulwaree Council community bike ride

Tallong public school numeracy award

Pejar Local Aboriginal Land council yarning circle

Supported upgrade of basketball court and Tallong skate park

There are a few teams entered into the Goulburn Golf Day.

Plans for next three months

PTQ

Safety

Focus on new "lifesaving commitments" – particular focus on one per month as part of the morning toolbox talk

Overburden

Continue to strip in a Southerly direction and utilising the MSL area to deposit material

Pit Update

Metso has been realigned to follow overburden stripping in a Southerly direction

Processing (STQ)

Continue to supply aggregates and sand to Sydney metro. There has been an increase in sand yield on Peppertree for the cement market. Up to 50,000 tonnes per month – working with MSL as a joint venture to supply our concrete business. Access to fine sand is reaching a major shortage.



	MSL
	Safety
	Focus on the behavioural safety. There are three components SOP, leadership and people taking personal ownership. Safety is a key focus for the site.
	Overburden
	Overburden placement to begin, post final management plan approval, extending the western emplacement and adjacent to lime plant
	Pit Update
	Also waiting on final approval of management plans and mining lease before extension to the west.
	People
	Our Maintenance department will be advertising for 2 apprentices, a welder and a fitter as well as an electrical tradesperson.
General Business	Boral was asked what mitigation measures do Boral use regarding landslide assessment?
	MSL – we have a Geotech company that is engaged on an annual basis for site inspections,
	they look at all slopes and all overburden and mine plans are approved by that company as well.
	We do have minor wash a ways from time to time. This is a front of mind issue for the mine. Local Land Services are visiting both sites to give some advice on soil erosion management
	PTQ - is very similar they have an independent company visit the site once a year to assess the
	high walls and bases.
	Supervisors do a daily drive around to ensure no movement in the quarry.
Actions	
Next Meeting	March/April
Meeting Close	3:56pm and was followed by a site tour at MSL